


TIMER/POWER SUPPLY

1. FASTEN THE POWER SUPPLY BOX IN THE AREA DESIRED, SCREWS INCLUDED.
2. ONCE THE BOX IS SECURE- PLACE BATTERY IN BOX- HOOK THE LEADS- RED TO RED, BLACK TO BLACK
3. PLUG IN POWER SUPPLY TO ANY 110 VAC GROUNDED OUTLET
4. 2 LEADS ON BOTTOM OF BOX HOOK TO THE 2 LEADS ON THE ELECTRICAL MORTISE.
5. SET TIMER- THE INSTRUCTIONS FOR THE TIMER ARE INCLUDED IN THE BOX.
6. NOTE: WHEN THERE IS NO POWER TO THE ELECTRONIC MORTISE THE MORTISE WILL REMAIN LOCKED.

3 PRONG ELECTRICAL PLUG- PLUG INTO ANY 100VAC SOURCE



CONNECT BATTERY- RED TO RED, BLACK TO BLACK

2 LEADS- HOOK TO MORTISE LEADS- POLARITY NOT IMPORTANT (12 VDC)

SEE <http://www.youtube.com/watch?v=6oq6duV0n0E&feature=youtu.be> FOR FUNCTION OF BOX AND LOCK

<h1>TownSteel</h1> <p>17901 RAILROAD STREET CITY OF INDUSTRY, CA 91748</p>	DRAFT UNLESS OTHERWISE SPECIFIED: 1° MAX	A	<p>TOLERANCES UNLESS OTHERWISE SPECIFIED:</p> <p>X.X (METRIC) = ±0.4</p> <p>X.XX (METRIC) = ±0.15</p> <p>FRACTIONS = ±.03</p> <p>ANGLES = ±1/2°</p> <p>© .12</p> <p>MACHINED SURFACES 125/</p> <p>⊕ THIRD ANGLE</p>	MATERIAL: TL-100-UL
	DRAWN BY: SC			HEAT TREAT: N/A
	DATE: 5/20/13			FINISH: N/A
				TITLE: TIMER POWER SUPPLY, INSTRUCTIONS
				PART#: TIMER/POWER SUPPLY

THIS DRAWING AND THE INFORMATION CONTAINED THEREON OR DERIVED THEREFROM ARE THE CONFIDENTIAL PROPERTY OF TOWNSTEEL, INC. IT IS NOT TO BE REPRODUCED, OR DISCLOSED TO OTHERS, AND MAY BE USED ONLY FOR THE PURPOSE OF ENABLING THE PARTY TO WHOM IT HAS BEEN LOANED TO QUOTE ON OR FILL AN ORDER FOR TOWNSTEEL, INC., OR AS MAY BE OTHERWISE AUTHORIZED BY TOWNSTEEL, INC. IN WRITING.

NOTES: